

Cooks Point Well
Camera Survey

T.D. of Camera Survey 1236 ft
Screen from 1104' – 1236'

Location of obstruction
caused by overheating pump motor





0136.7ft



0136 .7ft



0136.7ft



0136.7ft